

Serial Number Window: Z8RZ07183

Build Date 22/Oct/2008

✘	Technical Type	696004322 - MX275, 4WD CAB TIER 3
✘	Variante	420529000-DRAWBAR, HEAVY DUTY
✘	Variante	420049000-CAB, NORTH AMERICA LUXURY
✘	Variante	420804000-AM/FM/WB RADIO - NAO
✘	Variante	420268000-NAO LEATHER/HTR SEAT
✘	Variante	420811000-STANDARD MUFFLER
✘	Variante	429307000-CODI DISPLAY MOUNTING KIT
✘	Variante	420820000-EXTERNAL MIRRORS,REMOTE WIDE A
✘	Variante	420829000-HYDRAULIC RETURN
✘	Variante	420099000-BEACON LIGHT RH/LH - EUR
✘	Variante	420794000-40KPH TRANSMISSION REDUCED RPM
✘	Variante	846645400-D 480/80R46 R1 W/16X46 FS NAO
✘	Variante	420301000-STD FLOW HYD SYSTEM
✘	Variante	420783000-GUIDANCE READY,STD 12BOLT AXLE
✘	Variante	420787000-CAB ISO11783
✘	Variante	420823000-TRUE GROUND SPEED SENSOR

✘	Variante	420014000-PERFORMANCE INSTRUMENTATION
✘	Variante	420990000-NO TIRE BRAND PREFERENCE
✘	Variante	420026000-WORKLIGHTS- HAL CAB/HAL BELTLI
✘	Variante	420826000-MONITOR MOUNTING
✘	Variante	420306000-FUEL TANK - 180 GAL.
✘	Variante	420334000-SMALL FRAME, 6 WTS, 1000
✘	Variante	420362000-2.55 WIDE REAR FENDERS
✘	Variante	
✘	Variante	420519000-3PTH SOLID BALL EDC- 5900KG
✘	Variante	420701000-NORTH AMERICA
✘	Variante	887645700-D 380/85R34 R1 W/13X34 FS NAO
✘	Variante	429175000-DUAL SPEED PTO
✘	Variante	
✘	Variante	420218000-AXLE, 120-4INCH
✘	Variante	420874000-BLOCK HEATER NAO
✘	Variante	420223000-FRONT AXLE HEAVY DUTY 40KPH
✘	Variante	420235000-MFD NARROW FENDERS
✘	Variante	420402000-4 CIRCUIT REMOTES W/FLOW CNTL
✘	Variante	DEFAULT_24-NO SELECTION

✘ Variante DEFAULT_471-NO SELECTION - PARTS INCLUDED

✘ Engine Serial Number 46952117

3105 Eagle Avenue
 Rock Valley, IA 51247
 www.townandcountryimpl.com

Town & Country IMPLEMENT

Phone: 712-476-2731
 Fax: 712-476-5338

RO: 42043R
Invoice: 53253R
Date: 03/14/2024

DAVE HULSTEIN
 2630 180TH ST
 ROCK RAPIDS 51246

Year		Make/Model		Serial Number		
2008		CIH 275		Z8RZ07183		
Stock No	PO	Hours	Tag	Customer	Telephone	
45678			NA	13061	712-472-3061	

Cond	OpCode	T	Description	Quantity	List	Net	Total
------	--------	---	-------------	----------	------	-----	-------

Type: TRACTOR RO Open Date: 02/05/24 Meter In: 2795

001 **SERVICE INSPECTION**

C SERVICE INSPECTION

F 2795 HOURS

WARMED UP AND BROUGHT INSIDE

DRAINED ENGINE OIL, CHANGED ENGINE OIL AND FILTER

REMOVED ALL 5 DRAIN PLUGS FOR HYD OIL, CHANGED HYD FILTER AND TRANS FILTER

FILLED HYD OIL

CHANGED FUEL FILTER

CHANGED WATER SEPARATOR

CHANGED CABIN AIR FILTER

CHANGED CABIN RECIRCULATION FILTERS

CHANGED INNER AIR FILTER

CHANGED OUTER AIR FILTER, CUSTOMER HAD ONE

CHANGED COOLANT FILTER

CHANGED OIL IN FRONT HUBS

CHANGED OIL IN FRONT PLANETARY

WENT THROUGH INSPECTION

CHECKED ALL FUNCTIONS

FOUND HOOD SHOCKS DIDN'T HOLD THE HOOD ALL THE WAY OPEN,

FOUND THE ENGINE OIL PAN WAS JUST STARTING TO SEEP, NO DRIPS YET (NOT A FULL LEAK SO DIDN'T FIX)

FOUND THE 3-POINT MOUNTING BOLTS WERE LOOSE UNDER THE TRACTOR, TIGHTENED THEM

FOUND THE WATER PUMP WAS LEAKING

FOUND EXHAUST MANIFOLD SHIELD WAS LOOSE, BOLT FELL OUT, PUT A NEW BOLT IN PLACE TO HOLD SHIELD TIGHT

THE UPPER RADIATOR HOSE WAS RUBBING ON THE FAN SHROUD AND IT ABOUT RUBBED THROUGH

STARTED TO CRANK SLOWLY WHEN PRIMING THE FUEL SYSTEM, PUT A BATTERY CHARGER ON IT, DISCONNECTED THE BATTERIES, AND LOAD-TESTED THEM, THEY WERE BAD BUT CHARGED THEM UP SO IT WOULD STILL START

CUSTOMER GAVE THE GO AHEAD ON A FEW REPAIRS

-TOOK THE OLD HOOD SHOCKS OFF AND PUT THE NEW ONES ON

-DRAINED THE ALL THE COOLANT OUT OF THE TRACTOR

-REMOVED THE UPPER RADIATOR HOSE THAT WAS ALMOST WORN THROUGH AND REPLACED WITH A NEW ONE

-TOOK THE TENSION LOSE FROM THE BELT ON THE FRONT OF THE ENGINE AND REMOVED THE BELT

-TOOK THE OLD WATER PUMP OFF

-PUT THE NEW WATER PUMP BACK ON WITH A NEW SEALING O-RING AND

3105 Eagle Avenue
 Rock Valley, IA 51247
 www.townandcountryimpl.com

Town & Country IMPLEMENT

Phone: 712-476-2731
 Fax: 712-476-5338

RO: 42043R
Invoice: 53253R
Date: 03/14/2024

DAVE HULSTEIN
 2630 180TH ST
 ROCK RAPIDS 51246

Year		Make/Model		Serial Number		
2008		CIH 275		Z8RZ07183		
Stock No	PO	Hours	Tag	Customer	Telephone	
45678			NA	13061	712-472-3061	

Cond	OpCode	T	Description	Quantity	List	Net	Total
------	--------	---	-------------	----------	------	-----	-------

THE BELT ON AND TENSION THE BELT
 -FILLED UP THE TRACTOR WITH COOLANT
 -AFTER CHARGING BOTH BATTERIES OVER NIGHT TOOK THE BATTERIES
 OUT OF THE TRACTOR AND BROUGHT TO PARTS TO GET TESTED
 - BATTERIES ARE RATED AT 950 CCA. 1ST BATTERY HAD 400 CCA AND
 SECOND BATTERY AT 450 CCA
 -PUT THE NEW BATTERIES IN THE TRACTOR AND PUT THE BATTERY COVER
 BACK ON
 -RAN TRACTOR AND CHECKED FOR ANY LEAKS AND DID NOT FIND ANY
 -BROUGHT TRACTOR TO THE WASHABY AND SPRAYED IT OFF WHERE OIL
 WAS SPILLED
 -LET TRACTOR GET UP TO OPERATING TEMP AND CHECKED FOR LEAKS AND
 DID NOT FIND ANY
 -PARKED TRACTOR FOR CUSTOMER PICKUP

CL	L	CUSTOMER LABOR		1450.00
		CUSTOMER LABOR		
	P	BF1385-SPS FUEL/WATER	1.00	40.40
		FUEL/WATER SEPARATOR SPIN-ON WITH DRAIN, SENSOR PORT AND RE		40.40
	P	84476647 FILTER	1.00	74.40
		INNER AIR FILTER MX 215,245,275,305 & EARLY MAGNUM 215,245,		
	P	293615A1 FILTER,MX2	2.00	40.70
		FILTER,MX240 CAB REC		81.40
	P	51508555 FILTER HY	1.00	114.00
		FILTER HYDRAULIC OI		114.00
	P	48142231 FILTER HY	1.00	86.50
		FILTER HYDRAULIC OI		86.50
	P	84605017 FILTER,WAT	1.00	21.00
		WATER FILTER		21.00
	P	84301243 FILTER, EN	1.00	99.75
		FILTER, ENGINE OIL		99.75
	P	84477358 FILTER, FU	1.00	30.50
		FILTER, FUEL		30.50
	P	87684088 FILTER, EL	1.00	56.43
		FILTER, ELEMENT		56.43
	P	73344316 OIL HYDRA	4.00	30.25
		OIL HYDRAULIC		121.00
	P	87386500 GAS STRUT	2.00	95.75
		GAS STRUT		191.50
	P	73344410 ANTIFREEZE	3.00	31.00
		ANTIFREEZE 50/50		93.00
	P	84246483 HOSE	1.00	153.05
		HOSE		153.05
	P	FREIGHTIN FREIGHT	1.00	23.56
		FREIGHT IN		23.56

3105 Eagle Avenue
 Rock Valley, IA 51247
 www.townandcountryimpl.com

Town & Country IMPLEMENT

Phone: 712-476-2731
 Fax: 712-476-5338

RO: 42043R
Invoice: 53253R
Date: 03/14/2024

DAVE HULSTEIN
 2630 180TH ST
 ROCK RAPIDS 51246

Year		Make/Model		Serial Number		
2008		CIH 275		Z8RZ07183		
Stock No	PO	Hours	Tag	Customer	Telephone	
45678			NA	13061	712-472-3061	

Cond	OpCode	T	Description	Quantity	List	Net	Total
			P 87453208R REMAN-WATE	1.00		191.00	191.00
			P CORES: Core Chrgs	1.00		25.00	25.00
			P 87453208C CORE-WATER	1.00		-25.00	-25.00
			REMAN-WATER PUMP				
			P BMF31GW 12V 1000CC	2.00		183.24	366.48
			P CORES: Core Chrgs	2.00		21.00	42.00
			P SCRP3 CORE	2.00		-21.00	-42.00
			12V 1000CCA 36MO				
			P 73344237 15W40 BULK	6.50		16.70	108.55
			15W40 BULK				
			P 73344270 HYTRAN	45.00		18.70	841.50
			BULK HYTRAN				
			P 73344317 85W140 5GA	1.00		140.00	140.00
			85W-140 GEAR OIL				
			O HRD HERITAGE EQUIP DISCOUNT	11.00		-20.00	-220.00
			Subtotal charges this section				4064.02
			 M SHOP SUPPLIES				 31.85

THANK YOU FOR YOUR BUSINESS

CHARGE 13061 4273.25

I hereby authorize the above repair work to be done, along with necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other cause beyond your control. "By signing, I certify that I am authorized to use this Account, to sign this receipt, and that I agree that the total amount of this invoice is repayable in accordance with the Credit Agreement applicable to the Account". Signature: _____	DESC	TOTALS
	LABOR	1450.00
	PARTS	2834.02
	SUBLET	
	MISC	31.85
	OTHER	-220.00
	SUBTOTAL	4095.87
	TAX	177.38
TOTAL	4273.25	